


51 12 460**Replacing rear bumper panel trim strip**

Release all latch mechanisms (1) along the dotted line on the inside of the bumper panel.

Removing trim strip (2) from bumper panel.