

51 01 99 (392)

Windscreen wipers making noises

All models

Complaint:

Windscreen wiper blades scraping.
Wiping area is not properly wiped.

Cause:

- When the windscreen is dirty and greasy, the windscreen wipers increasingly tend to scrape.
- The wiper arm contact angle is not set correctly.
- Wiper blade faulty - worn

Affected vehicles:

All models

Remedy:

Check for all of the causes listed above.

Procedure:

- Clean the windscreen and wiper blades with BMW silicone remover.
- Check and if necessary adjust the contact angle of the wiper blades to the windscreen using the special tool.

See Repair Instructions 61 61 010.

- Check the wiper blades for damage. Replace them if necessary.

Important notes:

- Only disassemble the wiper arms using the appropriate special puller.

See Repair Instructions 61 61 100.

- Broken wiper arms are not covered by the vehicle warranty.

Important note for the German market:

- Wiper blades must be cleaned and sent in in the original packaging, otherwise they cannot be replaced.

Parts:

Order number for special tools

Description	Order number	Vehicle type
Wiper arm puller	61 6 060	all model series
Wiper arm puller	61 6 000	E36, E38, E39
Contact angle test gauge	00 9 230	E36, E38, E39
Contact angle	00 9 331	E46

test gauge

Wiper arm setting tool	00 9 261 / 00 9 262	E39
---------------------------	---------------------	-----

Wiper arm setting tool	00 9 220	E36, E38
---------------------------	----------	----------

Wiper arm setting tool	00 9 332 / 00 9 333	E46
---------------------------	---------------------	-----

Silicone remover	83 19 9 407 906	
------------------	-----------------	--