



ST(RPD)-01


TO POWER SUPPLY CIRCUIT
ST-1
F/B FUSE NO. 21
(B)
ST-2
STARTER
CUT RELAY
WL
WB
CLUTCH
START
SWITCH
B106
STARTER
RELAY
B225
MULTI JOINT
CONNECTOR
B439
B444
B434
SHORT
CONNECTOR
B181
B182
OP JOINT
CONNECTOR
B251
B252
BATTERY
STARTER MOTOR
B14
A: B134 B: B135 ECM


B106
B181
B251
B434 (PINK)
B439 (GREEN)
B444 (LIGHT GREEN)
B: B135 (BLACK)


B225 (BLACK)
RELAY BLOCK


A: B134 (BLACK)