


TO POWER SUPPLY CIRCUIT		
MB-19 M/B FUSE NO. 9	MB-20 M/B FUSE NO. 9	MB-21 HORN RELAY



ST3							
1	2	3	4	5	6	7	8

B68													
1	2	3	4	5	6	7							
8	9	10	11	12	13	14							