


## 3. Super Multiple Junction (SMJ)


### A: HOW TO USE SUPER MULTIPLE JUNCTION (SMJ)

The "SMJ" indicated in wiring diagrams is shown in a simplified form.

### B: TERMINAL ARRANGEMENT



### C: INSTALLATION



#### Tightening torque:

**T: 4.4 N·m (0.45 kgf·m, 3.3 ft·lb)**


#### NOTE:

- Align the cutout portion of one connector with that of other before tightening the connecting bolt.
- Do not tighten the bolt excessively since this may deform the connectors.

SUPER MULTIPLE JUNCTION (SMJ)

WIRING SYSTEM

D: EXPLANATION OF SMJ SHOWN IN THE WIRING DIRAM



cardiagn.com

MEMO: