




[Body H/B]




[Body W/G]




[Engine Compartment]



○ 1 : Engine Room R/B No. 1	Left Engine Compartment
● : Engine Room J/B No. 1	




Unit A




cardiagn.com

① : Engine Room R/B No. 1	Left Engine Compartment
② : Engine Room J/B No. 1	

Unit A





Unit B





[Engine Room R/B No.1 and Engine Room J/B No.1 Inner Circuit]


* 1:May 2015 or later


















: Instrument Panel J/B Assembly

Instrument Panel Reinforcement




[Instrument Panel J/B Assembly Inner Circuit]



(Cont. Next Page)

[Instrument Panel J/B Assembly Inner Circuit]


(Cont'd)



(Cont. Next Page)

[Instrument Panel J/B Assembly Inner Circuit]

(Cont'd)




(Cont. Next Page)

[Instrument Panel J/B Assembly Inner Circuit]

* 1:Driver's Door Only Jam Protection
 * 2:4-Door Jam Protection


(Cont'd)




(Cont. Next Page)

[Instrument Panel J/B Assembly Inner Circuit]

(Cont'd)



[Instrument Panel]



[Instrument Panel]

