

ATTENTION:

GENERAL MANAGER ☐
 PARTS MANAGER ☐
 CLAIMS PERSONNEL ☐
 SERVICE MANAGER ☐

IMPORTANT - All
 Service Personnel
 Should Read and
 Initial in the boxes
 provided, right.

**SUBARU**

QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2013MY BRZ
 2010-2014MY Forester
 2012-2013MY Impreza
 2010-2013MY Legacy/Outback
 2010-2013MY Tribeca
 2012-2013MY Impreza WRX/STI

NUMBER: 18-171-13**DATE:** 04/30/13**SUBJECT:** Service Manual Corrections**INTRODUCTION**

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2013	Legacy & Outback	Engine 1	FU(H4DO)-6	New Image to include Cam Sensor Spacer.
			ME(H4DO)-8,9	New Image to include Cam Sensor Spacer.
			EN(H4DO)(diag)-186, 188	Diagnostic steps changed for DTC's P0327 & P0328.
		Engine 2	ME(H6DO)-74,75,78	New images for Chain installation.
			EN(H6DO)(diag)-228,230,232,234	Diagnostic steps changed for DTC's P0327, P0328, P0332 & P0333.
2012	Legacy & Outback	Engine 1	EN(H4DO)(diag)-176, 178	Diagnostic steps changed for DTC's P0327 & P0328.
		Engine 2	EN(H4DOTC)(diag)-173, 175	Diagnostic steps changed for DTC's P0327 & P0328.
		Engine 3	ME(H6DO)-75,79	New images for Chain installation.
2011	Legacy & Outback	Engine 3	ME(H6DO)-71,75	New images for Chain installation.
2010	Legacy & Outback	Engine 3	ME(H6DO)-70,73,74	New images for Chain installation.
2013	Tribeca	Engine	ME(H6DO)-67,71	New images for Chain installation.
			EN(H6DO)(diag)-228,230,232,234	Diagnostic steps changed for DTC's P0327, P0328, P0332 & P0333.
2012	Tribeca	Engine	ME(H6DO)-65,66,69	New images for Chain installation.
2011	Tribeca	Engine	ME(H6DO)-60,67,70,71	New images for Chain installation.

Continued...

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2010	Tribeca	Engine	ME(H6DO)-62,63,66	New images for Chain installation.
2014	Forester	Engine 1	FU(H4DO)-6	New Image to include Cam Sensor Spacer.
			ME(H4DO)-8,9	New Image to include Cam Sensor Spacer.
			EN(H4DO)(diag)-180, 183	Diagnostic steps changed for DTC's P0327 & P0328.
		Engine 2	FU(H4DOTC)-7	New Image to include Cam Sensor Spacer.
			ME(H4DOTC)-7,8	New Image to include Cam Sensor Spacer.
			EN(H4DOTC)(diag)-217-224	Diagnostic steps changed for DTC's P0327, P0328, P0332 & P0333.
2013	Forester	Engine 1	FU(H4DO)-6	New Image to include Cam Sensor Spacer.
			ME(H4DO)-7,8	New Image to include Cam Sensor Spacer.
			EN(H4DO)(diag)-176, 178	Diagnostic steps changed for DTC's P0327 & P0328.
			EN(H4DO)(diag)-241	Diagnostic steps changed for DTC's P1449.
		Engine 2	EN(H4DOTC)(diag)-177,179	Diagnostic steps changed for DTC's P0327 & P0328.
			EN(H4DOTC)(diag)-267	Diagnostic steps changed for DTC's P1449.
2012	Forester	Engine 1	FU(H4DO)-6	New Image to include Cam Sensor Spacer.
			ME(H4DO)-7,8	New Image to include Cam Sensor Spacer.
			EN(H4DO)(diag)-241	Diagnostic steps changed for DTC's P1449.
2011	Forester	Engine 1	EN(H4DO)(diag)-223	Diagnostic steps changed for DTC's P1449.
2010	Forester	Engine 1	EN(H4SO)(diag)-188,190	Diagnostic steps changed for DTC's P0327 & P0328.
2013	Impreza	Engine	FU(H4DO)-6	New Image to include Cam Sensor Spacer.
			ME(H4DO)-8,9	New Image to include Cam Sensor Spacer.
			EN(H4SO)(diag)-175,177	Diagnostic steps changed for DTC's P0327 & P0328.
			EN(H4DO)(diag)-249	Diagnostic steps changed for DTC's P1449.
2012	Impreza	Engine	EN(H4DO)(diag)-239	Diagnostic steps changed for DTC's P1449.
2013	WRX & STI	Engine 3	EN(H4DOTC)(diag)-203,205	Diagnostic steps changed for DTC's P0327 & P0328.
			EN(H4DOTC)(diag)-307	Diagnostic steps changed for DTC's P1449.
2012	WRX & STI	Engine 3	EN(H4DOTC)(diag)-295	Diagnostic steps changed for DTC's P1449.
2013	BRZ	Engine Control	ES-630	New Image to include Cam Sensor Spacer.
		Manual Transmission/ Transaxle	MT-5,6,15,37	Many changes, review on STIS.
		Axle/ Differential	AD-40,41	Rear Diff Pinion Preload steps changed.