

Restraints

Seat Belts

Component Location Index	24-2	Seat Belt Inspection	24-8
Front Seat Belt Removal/ Installation	24-3	Child Seat Tether Anchor Installation '96-99 models	24-9
Rear Seat Belt Removal/ Installation	24-5	Child Seat Tether Anchor Removal/ Installation '00-04 models	24-10

Supplemental Restraint System (SRS)

Special Tools	24-13	Disconnecting the SRS Connector at the Fuse Box ('96-98 models)	24-28	Disconnecting the Airbag Connectors, Side Airbag Connectors, and Seat Belt Tensioner Connectors ('99-04 models)	24-32	Initializing the OPDS (Occupant Position Detection System) Unit '99-04 Models	24-88
Component/Wiring Location Index '96-98 models	24-14	Wiring Precautions	24-28	Steering-related Precautions	24-34	DTC Chart '96-98 Models	24-38
'99-04 models	24-15	Spring-loaded Lock Connectors	24-29	Troubleshooting Self-diagnostic Procedures '96-98 Models	24-35	'99-04 Models	24-89
Description SRS Airbag System '96-98 models	24-16	Spring-loaded Lock Connectors with Built-in Short Contact	24-30	Reading the DTC '96-98 Models	24-35	SRS Indicator Light Wire Connections '96-'98 Models	24-40
'99-04 models	24-17	Seats with Side Airbags ('99-04 models)	24-30	'99-04 Models	24-84	Fuse Box and Connector Locations '99-04 Models	24-92
Precautions/Procedures General Precautions	24-26	Backprobing Spring-loaded Lock Connectors	24-31	Erasing the DTC Memory '96-98 Models	24-37	Airbag Replacement	24-160
Airbag Handling and Storage	24-26	Disconnecting the Airbag Connectors and Seat Belt Tensioner Connectors ('96-98 models)	24-31	'99-04 Models	24-87	Side Airbag Replacement	24-164
Seat Belt Tensioner Handling and Storage	24-27			Troubleshooting Intermittent Failures '96-98 Models	24-37	Seat Belt Tensioner Replacement	24-165
SRS Unit ('96-04 models) and Side Impact Sensor ('99-04 models)	24-27			'99-04 Models	24-87	Airbag and Seat Belt Tensioner Disposal '96-98 Models	24-168
Inspection After Deployment	24-28					'99-04 Models	24-172
						Cable Reel Replacement	24-176
						SRS Unit Replacement	24-181
						Side Impact Sensor Replacement	24-183