

PGM-FI System

Engine Coolant Temperature (ECT) Sensor (cont'd)

P0117

The scan tool indicates Diagnostic Trouble Code (DTC) P0117: A low voltage (high temperature) problem in the Engine Coolant Temperature (ECT) sensor circuit.

