



Back up Circuit

P0560 ('00 - 01 model) The scan tool indicates Diagnostic Trouble Code (DTC) P0560: Low Voltage in PCM Back up Circuit.

NOTE: If the BACK UP RADIO (7.5 A) fuse is removed and the ignition switch ON (II), MIL will report on and PCM will store the DTC P0560.

