



AYGO

Exterior sticker decoration (Xme I)


Installation instructions

ALWAYS A
BETTER WAY

Model year:	2018/05	
Vehicle code:	KGB40*-AH**GKW	
Part number:	PW18A-0H006	(with roof sticker)
	PW18A-0H009	(without roof sticker)
	PW18A-0H010	(roof sticker)




Revision Record

Rev. No.	Date	Page	Picture	Update	New	Deleted steps
1	24.04.18	9, 12, 15, 20, 24, 26, 31-35, 36	7, 15, 23, 38, 46, 47, 51, 64, 66, 67, 70, 72, 74	X		
1	24.04.18	10, 13, 16, 18, 21, 25, 33, 36, 39	9, 17, 25, 32, 40, 48-50, 68, 75		X	
1	24.04.18	24, 25	43-45			X
2	21.06.18	1, 2, 3, 4, 37, 41		X		
2	25.06.18	36	78		X	






PW18A-0H006









PW18A-0H009

A	LHS		1x	RHS		1x
B	LHS		1x			
	RHS		1x			
C	LHS		1x			
	RHS		1x			
D	LHS		1x	RHS		1x
E						1x
F						1x

PW18A-0H010


H			1x	J		1x	K		1x
----------	--	--	----	----------	---	----	----------	---	----












Material Safety Data Sheet





Technical Data Sheet




1  25°C 15°C 	2  	 
---	--	---




1  25°C 15°C 	2  	 
---	--	---






2






3







4






5




6




7




8





9






10






11







12






13




14




15




16




17




18




19



20




21






②


Diagram 2 illustrates the correct and incorrect ways to perform a 180-degree turn. The left side shows a correct 180-degree turn, marked with a checkmark and a warning triangle, indicating a safe maneuver. The right side shows an incorrect 180-degree turn, marked with a large X, indicating a dangerous maneuver. A snail icon is present in both diagrams, likely representing a slow or cautious approach.





TOYOTA




24




25




26





27





28




29




30




31




32






33





34






35





36



37




38




39


40




41




42




43







44






45






3


46




47




48





49







50






51




52







57




58




59









63







64


65




66










70




71




72







73





74




75



76



77









78



OWNER MANUAL


INSTALLATION DATE:/...../.....

INSTALLATION TIME:/...../.....



OWNER MANUAL





TOYOTA





**Exterior sticker decoration
(Xme I)
Aygo
2018/05
AIM 004 191-1
KGB40*-AH**GKW**





**Print 100%
Check with Rulers
before use.**






TOYOTA













ALWAYS A
BETTER WAY

Model / Year AYGO 2018/05

Exterior sticker decoration (Xme I)





[illegible]

OWNER MANUAL



= OK

LHS

**Installation Date:**

. . / . . /

Technician Name & Signature:

Stamp: